GOVERNMENT OF INDIA

ARCHÆOLOGICAL SURVEY OF INDIA

CENTRAL ARCHÆOLOGICAL LIBRARY


ACCESSION NO. 22535 CALL No. 913.013/T.D.A.

D.G.A. 79

Office of Bir, Genl. of Archivology.
SIMLA CENTRAL LIBRARY.

Division

No.





Cobernment of Bengal.

PUBLIC WORKS DEPARTMENT.

LIST OF ANCIENT MONUMENTS

IN THE

DACCA DIVISION.

Revised and corrected up to 31st August 1895.

PUBLISHED BY AUTHORITY.


22535



S THE DIRECTOR GENERA D 5 90 Morary Regr No


Calcutta:


PRINTED AT THE BENGAL SECRETARIAT PRESS.
1896.



DACCA DIVISION.

CENTRAL ARCHAEOLOGIGAE
LIBRARY, NEW DELHI.
Acc. No. 22535
Date 10 2 Se
Call No. 913 073/1 D. A





CLASSIFI

[See Government of India, Home Department,

I.—Those monuments which, from their present condition and historical or II.—Those monuments which it is now only possible or desirable to save the exclusion of water from the walls, and the like.

III .- Those monuments which, from their advanced stage of decay or

I. (a) and II (a).—Monuments in the possession or charge of Government, conservation.

conservation.

I. (b) and II (b).—Monuments in the possession or charge of private

(I) DACCA

No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
1	Dacca	Dacca	Lálbágh Fort Bibi Peri's Mansoleum.	This was commenced in 1678 by Sultán Muhammad Ázam, third son of Aurangzeb, but was never finished. The old gateways and battlements still remain. They form a very picturesque feature in the land-scape when viewed from the river which washes one solid bastion. Situated within the Lálbágh enclosure. It was erected towards the end of the 17th century by Nawab Shaista Khán, successor of Sultán Muhammad Ázam, in memory of the Nawab's daughter, Bibi Peri, wife of Muhammad Ázam. The tomb lies within a building which has a vaulted roof of sandstone slabs, and an ornamented floor of marble and basalt; its walls are of brick faced inside with marble. The central dome is protected outside by a covering of sheet copper. The building is one of architectural importance and is unique in Lower Bengal. There is a two-storied building in the middle of the Lálbágh Fort, apparently of ancient date. It has stone pillars and vaulted roof.
2	Do	Do	Husseni Dalan Palace. Tomb of Nawab Nasarat-jang. Tomb of Nawab Samsadwala. Tomb of Nawab Kamaradawala, son of the former. Tomb of Nawab Gaziudd in Hyder, son of the former.	These Nawabs died in the beginning of the 19th century. Their graves he in one building situated within the compound of the Hussen Dalan. They have no inscriptions.

DIVISION.

CATION.


Resolution No. 3-168-83, dated 26th November 1883.]


archæological value, ought to be maintained in permanent good repair. from further decay by such minor measures as the eradication of vegetation,

comparative unimportance, it is impossible or unnecessary to preserve—
or in respect of which Government must undertake the cost of all measures of
bodies or individuals.

DISTRICT.


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
Used as a Police Tháná	The old gateways and battlements are in bad condition, being overgrown with jungle and trees and much affected by the action of saltpetre. They need preservation and require urgent repair.	iia	See pages 127 to 131 of Vol XV of the Archaelogical Survey Reports. See also pages 66-67 of Hunter's Statistical Account of the Dacca district. Bishop Heber visited Dacca in July 1824.
*****	Well worthy of preservation. Some repairs are needed to it, which should be carried out.	ia	duly 1001
	10 10 14		
Is now occupied by the Police Department as a thana.	Is in good condition, being maintained by the Public Works Department.	ia	
Used for religious ceremonies, especially in the Muharram. Government assumed charge of it, which has been delegated to Nawab Ashannullah c.i.e., to whom Government pays an annual grant, which the Nawab largely supplements from his private funds.	from the Government grant supplemented by himself.		
These tombs are under the custody of Nawab Ashannul lah, c.i.e.	The building is in good condi- tion and is maintained and repaired at the expense of Government, through Nawal Ashannullah, c.i.e., to whom as annual grant, dating from before British times, is conti- nued by Government.	f b a	






-			P. 100	
No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
3	Dacca	Dacca	The chak (market place)	
4	Do	Do	Idgah of Mir Abdul Kássim.	This is a lofty masonry wall with prayer niches standing on the western part of the town near the Pilkhana. It was built in 1640 by Mir Abdul Kasim, household Diwan of Sultan Sujah.
ō	Do	Do	Great Katra (caravanse-rai).	This was built by Mir Abdul Kásim Khán under the orders of the Prince Azimushan during the latter's Viceroyalty of Bengal in the year 1645 A.D. It is said that it was intended for travellers and was to serve the purpose of a caravanserai. It is a building of enormous massiveness and solidity, and will not rapidly fall into decay. The building from its dimensions looks imposing from the river; the main gateway facing the river is picturesque. On its completion the Prince inspected it, but did not like it, and gave it to Mir Abdul Kásim.
6	Do	Do	Small Katra (caravanserai).	This was built by Amiral Omrah, Nawab Shaista Khan, on his succeeding prince Azimushan as Viceroy of Bengal. It is said that it was intended for a curavanseral and was built some years after the great Katra, but the exact year is not known. It looks well from the river having one fine doorway facing in that direction.
7	Do	Do	Temple of Dhákesvari.	A Hindu temple, of considerable celebrity, sacred to the goddess of Dacca (Dhákesvarf). This is the temple of the tutelary deity of Dacca, and is according to the local tradition very ancient.
8	Do	Ditto (Shahbag, a Park of the Nawab's north of Dacca.)	Tomb	This is an old tomb in a park belonging to Nawab Ashanullah, c.r.e., of Dacca. Nothing is known about the history of the tomb or the person interred within it. The building which contains the tomb is a quadrangular hall on a low plinth, with the grave in its centre built in masonry. The hall measures 25' × 18' and is open on all sides and supported by rectangular pillars spanned by semi-circular arches. The hall is roofed over by a vault with a small rise, so that the building looks flat-roofed from outside. The whole outer face of the building is covered with ornamental work in plaster.
9	Do	Dacca (Ramná)	Mosque of Háji K a h j e h Shahabag.	This mosque is said to have been built 200 years ago by Háji Kahjeh Shahabag, a merchant of Kashmir. It is said that he originally came from that place and settled in the town of Dacca, where he prospered in trade. The mosque, which stands on the SW. of Ramná, is a quadrangular building of brick masonry 67' × 26' on the outside, roofed over with three domes, and ornamented at the corners with eight minarets, which are


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
Market is held every afternoon within the enclosure.	The wall is in a bad state of repair.	iii	Ç
n custody of the local Muham- madans. Still used for reli- gious ceremonies during the Id festival.	It requires repairs	ib	
In private hands; pretty well looked after.	Nearly if not quite intact and not likely easily to fall into decay.	iib	
It is in private hands and is pretty well looked after.	It is substantial and not likely easily to fall into decay.	iib	
*****	Has been lately repaired and is in good condition, the recent repairs having greatly improved its state.	ib	
In custody of Nawab	Good. The Nawab has lately repaired it.	iib	
It is under the custody of Jaga Shah Saheb of Muhalla Beobá- rám Dewri, Dacca, who looks after the mosque and provides it with lights and mats. It is still used as a place of wor-	work have decayed, and vegeta- tion and trees have grown over the building. To carry out thorough repairs a sum of		
ship.			






No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	. 3	4	5
			Tomb of Háji K a h j e h Shahabag.	mostly broken. The outside course of the plinth at the level of the floor is built of long blocks of basalt, carved in the shape of a neat frings. The door frames are also of basalt. There are three doors on the eastern, i.e., the front, side of the mosque and one each on the north and the south sides. The door openings have neat pointed arches. The masonry of the whole structure, though very old, is strong. Attached to the mosque and close to it lies the tomb of its founder, Háji Kahjeh Shahabag. It is said that the mosque and the tomb were built at one and the same time by their founder, and that after his death his body was interred within the tomb. The building which contains the tomb is a square one measuring 26' outside and surmounted by a single dome and four minarets.
10	Daces	Dacca (Thatari Bazar).	Temples of Jayakáli and Sivu.	These temples are of considerable celebrity. The centre temple is a small terrace-roofed building 22' × 20' dedicated to the God Siva with two large temples on each side. In it is the image of the goddesa Káli, a very fine specimen of soulpture in stone. Of the side temples the western one is a "Pancharatna," or a temple with five towers, of which the centre one is about 50 feet high, with side ones of a smaller height. The eastern temple stands on a base 12 feet square and rises in a single spire to a height of about 70 feet, and it can be seen from a great distance. The temples are of very solid construction, and ornamented outside with carved work in brick and plaster. They are about 200 years old. There stood close by an older temple called "Navaratna," which was 250 years old and which collapsed about 12 years ago. The railway line now runs close in front of the temples which stand up picturesquely as viewed from the train.
11	Do	Ditto (Armenian Street.)	Armenian Church of the Holy Resur- rection.	In the early part of the eighteenth century, the Armenians settled at Dacca in Eastern Bengal and formed a colony there, when it was one of the important commercial centres in Bengal. There they flourished in commercial pursuits for a considerable time, and amassed great riches. At first they built a small chapel, where they worshipped prior to the erection of the present church, and they lie buried in the cemetery at Tejgaon, where many an old tombstone with Armenian inscriptions can be seen. The oldest is to the memory of one Avetis, an Armenian merchant, who had died at Dacca on 15th August 1714. In 1781 the growing community erected the present Armenian church at Dacca in the locality known as Armanitola (Armenian Street) and dedicated it to the "Holy Resurrection." The ground was the gift of Agah Catchick Minas, and on it stood the small chapel already referred to.


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
In custody of the local Muham- madans.	The building which contains the tomb is much overgrown with trees and damaged in many places. The vestibule, which had a fine gabled arch of brick masonry, has fallen in. The necessary repairs can be carried out at a cost of Rs. 500.	iò	
The temples are resorted to by large numbers of people as a place of worship. There was once some landed property attached to them, but it has now been alienated for want of proper deed of gift.	The temples are very old and are overgrown with vegetation and trees. If the jungle were eradicated, the plaster renewed and the walls whitewashed, they would last for a long while. The cost of such repairs may be estimated at about 500 rupees, which it is not in the power of the present custodian of the temples to defray.	iib	
In use as a church, and is in the custody of a warden.	In good order	iŏ	See pages 151-152 of the History of the Armenians i
			India by Mesroyb J. Seth Armenian Examiner to the University of Calcutta.






No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
				In the early part of the present century the most eminent Armenian merchant and zemindar of Dacca was the famous Agah Arratoon Michael, who died a millionaire in 1824. The founder of the Dacca Pogose School, Mr. Nicholas Pogose, was another rich Armenian zemindar of Dacca. That once-flourishing colony is reduced to a few families only, as in the case of Bombay and Madras. The church contains some ancient inscriptions.
				There is an unfinished clock tower on the west of the Armenian church, under which are the graves of Hiripsimiah, who died on 15th February 1837, and of her husband Johanness Carrapiet Sarkies, who died 25th January 1854. After his wife's death, Mr. Sarkies erected in July 1837 a tower of small height upon the present base with a large bell. The bell broke in 1860 or 1861; Mr. Sarkies then had the bell tower broken down, indented for a large clock from England, and commenced building the present clock tower over the old walls of the bell tower. The work was delayed owing to mismanagement till Mr. Sarkies lost his reason, and subsequently died. The clock with his other properties was sold off after his death; the tower is still standing in an unfinished state. Though not of any antiquity, it is a conspicuous and interesting object in Dacca. Proposals are on foot for its completion by the Armenian residents of the place.
12	Dacea	Dacca (Cemetery)	Tomb of Colombo Saheb.	This is a lofty mausoleum situated near the tomb of the Joseph Paget, and is an octagonal building with a dome on the top. The inside measurement of each of the sides of the octagonal base is 5'-6". The height from floor to the highest point of the ceiling of the dome is about 40 feet, and the total height from the base to the ridge is about 46'. The structure is divided into three stages. The first or lower portion is 14 feet in height from the plinth. There are four doorways in it, each measuring 2'-8" by 6'-0"; there are also recesses on the remaining four sides measuring 4'-6" by 12'-0". There is an ordinary simple cornice on top of the first stage. The second or middle stage is also about 14' in height, and there are eight windows, one on each side, measuring 3'-6" by 8'-0"; these are fitted up with ornamental earthenware louvre work. There is a cornice on top of this stage like the one described for the first stage. The last stage or the top portion is a dome or cupola 12 feet in height. At each corner of the octagon there is an octagonal pillar on the outside surmounted by a vase like that generally to be found in Muhammadan mosques. There are also four pillars on the four corners of the circumscribed square, and these look like ordinary buttresses. There are three graves inside the structure without any inscriptions.


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
		11	
	It is opensorous with trees and	ib	
100141	It is overgrown with trees and has cracked in some places.		-
	9.0		
			7
	200		
	100		
he building is in the charge of the Public Works Depart- ment.	In good order	ia	See page 199 of Vol. I of Bishop Heber's Journals London, 1828.
-			
- 1 19	- 1 2		
13			
2011 100			






_				
No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
13	Daces	Dacea	Páglá bridge	On the 5th mile of the Dacca-Néráyangañ road, probably erected by Mir Jumlá, who became Vicercy of the Dacca province in 1660.
14	Do	Do	Tungi bridge	On the 14th mile of the Dacea-Mymensingh road. Probably erected by the same Viceroy as the above, the style of architecture being very similar. The bridge was blown up by order of the Magistrate of Dacea during the Mutiny. An engraving in Sir C. D'Oyly's Ruins of Dacea shows that one arch had fallen in many years before. A new iron bridge was built, but was carried away by the extraordinary high flood of 1890.
15	Do	Keránigañj (6 miles west of Dacca).	The Sat Gomal mosque.	This mosque is situated on the extreme edge of very high land on the borders of a deep and large swamp and is very picturesque. Strong revetment walls support the mosque on the west side, i.e., towards the swamp. There is a small enclosed courtyard in front of it, but the enclosure walls have fallen down, and the gateway is in ruins. There are other minor mosques and tombs in the vicinity, but they are in ruins and without any inscriptions, and no history of them can be traced.
				No history can either be traced showing the age or the founder of the Sát Gomal Mosque; there is no stone inscription or anything connected with the mosque which might give a clue to its history. The Mollah says that there was an engraved stone built over the central doorway of the mosque, but that when it was neglected and overgrown with jungle the stone was detached from the building and taken away by mischievous persons.
			*	The masjid is an oblong hall 48' x 16' feet inside measurement with four hollow, octagonal towers of 8' inside and 12' outside measurement. These are in two stories and are surmounted each by a dome. The main hall is also roofed over by three domes in the usual mosque fashion, and these three domes with the four others on the corner towers make in all seven in number, which give rise to the name of Sát Gomal Masjid, or the mosque of 7 domes. The building is ornamented both inside and outside with innumerable niches and recesses.
16	Do	Mirpur, tháná Keránigañj.	Tomb of Shah Ali Sábeb.	About 8 miles to the north-west of the town of Dacca, near the large village of Mirpur stands the Dargs or the Mausoleum of the saint Shah Ali Saheb. It is a square building 36 feet outside measuremnt and about the same in height with walls 7 feet thick and contains the tomb of the saint in its centre. The walls are surmounted by a single large tower with four small minarets at its corners. Over the central doorway are two stone inscriptions, one in


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
- 6	7	8	9
Abandoned, a new bridge having been erected about 50 feet east of it.	The bridge is in a dilapidated condition; the turrets which flanked it still stand on the banks. A very picturesque ruin.	iii	See page 202 of Vol. I o Bishop Heber's Journals London, 1828.
Abandoned	Remnants of the old structure are still standing.	iii	See footnote on page 121 o Hunter's Statistical Accoun of the Dacca district.
Under the charge of the local Muhammadans.	It was thoroughly reclaimed and repaired by Nawab Sir Abdul Gunny, K.C.S.L., about eight years ago, and it stands in every respect a practically new building. He also pays a monthly donation towards the maintenance of a priest who enjoys the produce of a piece of rent-free land of about 12 pakhis in area.	iib	
	100000	1	1// 1/19
It is still used as a place of worship, not only by the local Muhammadans, but by those coming from distant places.	is patronized by Nawab Sir		






-	4	1		
No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
				Tughra Arabic and the other in crnamental Persian character. Ink impressions of both these inscriptions have been sent to the Government Epigraphist. Nothing very particular is known in the neighbourhood about the saint. The current tradition is that about 400 years ago Shah Ali, a prince of Bagdad, having renounced the pleasures of the world, came with four disciples and lived in a small mosque at this place. He ordered his disciples not to disturb him in his devotions for 18 months and shut himself up in the mosque for the performance of penances without any food or refreshments. The time passed, and when only one day remained the curiosity of the disciples was excited by a noise within as if of some liquid boiling over a fire. They forced open the door and found nothing remaining of the saint except a pool of boiling blood. They remained transfixed when an aërial voice in the tones of the saint ordered them to inter the blood as his remains at the spot, which they did. The place became famous for its sanctity, and ever since pilgrims have been flocking in large numbers to offer their prayers before the tomb. Some time after his interment an unknown merchant, who made large profits in his business in the neighbourhood, attributing his fortunes to the mediation of the saint, built this present Dargá or Mausoleum on the spot.
17	Dacea	Naliganj (Nará- yangañj).	Kadam Rasul Fort and mosque.	This fort is traditionally supposed to contain a print of the prophet's foot, hence the name. The mosque said to contain the footprint is in fair condition. The two-storeyed gateway facing the river is a striking building.
18	Do	Hájigañj	Fort	This fort was erected by the Viceroy, Mir Jumla, to resist the incursions of the Mugha and Arakanese.
19	Do	Munshigañj	Fort	This fort was built during the time of the Emperor Aurangzeb for protecting the country from the invasion of the Burmese. Within the enclosure wall are situated the residence of the Subdivisional Officer of Munshiganj and the lock-up, the first of which is built upon the top of the chief bastion.
20	Do. ***	Soņakhaņda	Fort rains	This fort is situated at the junction of the Lakhya and Dhalesvari rivers. It stands opposite Náráyangaój on the east side of the Lakhya river. It is one of the three forts built for the purpose of repelling the invasious of the Mughs and Arakanese. It is a level quadrangular space measuring 296' x 190' surrounded by a wall of brickwork 10 feet in height with inner and intermediate bastions and a raised outwork on the western face. The wall is


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
	prayers at the Darga. He also keeps up a garden and a small tank in connection with the Darga, pays for a permanent guard, and offers regular donations for the festival occasions. He has also constructed two roads, one leading from the Juspar river and the other from the Dacca-Goalundo road to the Darga, and has thus made the place formerly embedded in jungle accessible both by land and water.		
/ -			
In private hands and much frequented by the Muhammadans of the district.	Is in good order, having been lately thoroughly renovated. The surrounding walls are dilapidated, but of no interest.	iib	
Belongs to Nawab Ashanullah, c.i.s. Has been utilized by the Nawab as the basis of a new building	The exterior walls of the fort and a bastion are standing.	iib	
It is under the custody of Government.	The enclosure wall and five bas- tions are still standing. These are in bad condition and are overgrown with trees and jungle and need repair, the cost of which will be about Re. 1,000.	îa	
Is in private hands and is the joint property of the local zamindars.	In a totally ruined state, being overgrown with pipul trees. The outwork in the front is in a ruined condition, and the conservation of the structure is impossible.	iii	






No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
				loop-holed for 3 feet from the top, the bottom being built solid. It is only 31 feet thick, and though standing for the most part, it is in a totally ruined state, being overgrown with pipul trees. The Lakhya river must at one time have flowed by the foot of the fort, but it is now about 300 feet distant.
	Dacca	Sonárgaon or Suvarusgrám.	*****	This is in the Narayanganj subdivision. It was the capital of a Hindu principality anterior to the invasion of Muhammad Bakhtiyar Khiliji, A.D. 1203. Coins have been discovered on which Sonargaon is designated "Hazrati Jalal," a title afterwards given to Mozimabad, which was made the mint city. During the 15th and part of the 16th centuries, Sonargaon was the capital of an independent monarchy. About the 16th century, the city swarmed with pirs, fakirs, and other religious mendicants to a greater extent than perhaps any other Indian city. Amidst the ruins and forests of modern Sonargaon it is said that at least 150 "gaddis" of fakirs are distinguishable.
				The following is a description of the old buildings of Sonargaon.
21	Do	Ditto (SW. of Mo- hulla Baghal- pur.)	Tombs of five Pirs (saints).	The sepulchres of the five pirs are placed parallel to one another, and are raised about four feet from the ground. The river Brahmaputra must in former days have flowed past them. It was at one time intended to cover the tombs with a roof, but the pillars were never raised more than a few feet. The age of these graves, the names of the holy men, and the country whence they came are unknown. The belief is that they came from the west. At the south-west corner of the enclosure is a small uninteresting mosque, which, like the tombs, is rapidly falling into ruins.
22	Do	Ditto	Tomb of Ghyas- uddin Azam Shah.	darga, on the edge of a filthy trench called 'Magh Dighi' is the so-called tomb of Ghyasuddin Azam Shah, King of Bengal, and correspondent of the poet Hafiz. This mausoleum formerly consisted of a pon-
				derous stone surrounded by pillars about five feet in height. The stones are all beautifully carved, and the corners of the slabs and the arabesque tracery are as perfect as on the day they left

Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remares.
6	7	8	9
******	*****	***	For account of the ruins of Sonárgaon,—see pages 135 to 139 of Vol. XV of the Archwological Survey Reports.
******	In a ruinous state. The wall surrounding the enclosure has fallen down in places, and several large jungle trees grow close to the tombs, and will ultimately destroy them.	iii	For an account of these tombs, &c., see pages 139 to 145 of Vol. XV of the Archwologi- cal Survey Reports.
Abandoned	The tomb has fallen to pieces. The iron clamps that bound the	ia	
	slabs together have rusted, and the roots of trees have under- mined the massive stones, some of which are missing. Con- servation desirable. The Col- lector will see if a subscription can be raised for its restoration.		







-				
No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
				the workman's hands. The stones are hard, almost black, basalt. At the head is a prostrate sandstone pillar half buried in earth. It was apparently used, when erect, as a cherákdán, or stand for a light. This tomb ought to be repaired, and the cost of doing so would be inconsiderable. There is no old building in Eastern Bengal which gives a better idea of Muhammadan taste, and there is none which, when properly repaired, would so long defy the ravages of time. The Muhammadans of Sonargaon are too poor to reconstruct it themselves. They take great pride in showing it, although they know nothing about it but the name of the Sultán who is supposed to be buried there, and they take every care that none of the stones are carried off. It is
23	Dacca	Maghrápárá, Sonárgaon.	Damdamá Fort	said that some of the stones were stolen at one time, and the offender was detected and punished with imprisonment. The village of Maghrápárá is considered by the natives of Sonárgaon to be the site of the ancient city. It has in its immediate neighbourhood several undoubtedly old buildings, and within a short distance is an eminence, which still bears the name of "Damdamá" or fort. This mound, which has a magnificent tamarind-tree growing on its top, is circular, but no traces of fortifications are visible. It was used for many years by the Muhammadans as their Asharkháná during the Muharram. On the tenth day all the garlands and ornaments
			Tomb of Munna Shah Darvesh.	that were made in place of táziyas were here collected to be admired by the people; the practice has died out, as the local Muhammadans have since became Ferazis or non-idolaters. In the small market village of Maghrápárá is the tomb of Munna Shah Darvesh. At the foot a light is always burned at night, and every orthodox Muhammadan, as he passes the tomb, stops and mutters a prayer. This saint, about whom nothing is known, is said to have lived at the same time as the more famous pir whose tomb stands a little to the north.
			Tomb of Sheik M o h a med Yasuf (Háfiz Sáheb).	This latter is called the darga of Sheik Mohamed Yasuf. It contains the tombs of the saint, of his son, and of his wife. It consists of two elongated dome-roofed buildings, each surmounted by two pinnacles or kalas said to have been covered with gold, of which no trace remains. These tombs are destitute of any ornament inside. They are kept scrupulously clean, and are covered with sheets. When a raiyat has reaped an unusually abundant harvest, he presents a few bundles of ripe rice at the tomb in token of gratitude. If any calamity, such as the illness of a member of his

DISTRICT-continued.


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
	Carlotte Committee		
	N. C. S.		
	******	iii	
	100	-	
	-	19	
-	- 4		
*****	*****	iiδ	
	1 1 - 1 - 1		
*****	******	iib	
	3	-	
		-	






No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	8	4	5
			ik.	family, is threatening, he brings rice or batasa, and prays the saint to avert the affliction. Hindus are as confident of the efficacy of this propitiatory offering, and as frequently employ it, as the Muhammadans.
			Mosque of Mohamed Yasuf.	Close to the tombs is a modern masjid, with a khutba, or inscription, dated A.H. 1112. It was probably erected by pir Mohamed Yasuf. Facing the mosque is a small graveyard enclosed by a brick wall. The graves are numerous, but none are of any importance. Inserted in the wall of the enclosure at the left hand side of the entrance, is a large black stone, measuring two feet by one and a half which most probably belonged to the original or older mosque. The natives believe that if a person has lost any property, he has only to put a coating of lime on this stone, and he will infallibly get the property back. It was covered with a coating of lime when examined in May and June 1895.
				On scraping off the plaster a beautiful Tughra in scription was found, with the name Jalaluddir Fatch Shah, A.H. 889. This is said to be the oldest inscription discovered in the Dacca district with the exception of the one in Bábá Adam' Mosque in Rámpal in Bikrampur, which bear the date A.H. 888.
			+	Close to the tomb of Mohamed Yasuf is a ruine gateway, called the naubatkhana, where musics instruments were sounded morning and evening, t announce to travellers and fakirs that a place of shelter was at hand. At the back of the moder mosque are the ruins of a house called the tabbise of treasury, where feasts were given by the Superint tendent or mutawalli of the mosque. Still further to the north-west are the ruins of the dwellings of the Khwandhars. It is only within late year that this building, which had an upper room a each end, has become uninhabitable. The last residents taught boys to recite the Korán.
24	Daces	Maghrápárá, Sonárgaon.	Tomb of Shah Ābdul Ala.	In the mahalla north of Maghrápárá, called Gohatte is the tomb of a very celebrated pir, known as Sha Abdul Ala, alias Ponkai Diwanah. It is narrate that he retired to the forest, where he sat for twelv years so absorbed in his devotions that he was un conscious of the lapse of time. When found, the ha to be dug out of the mound which the white and (poka) had raised around him, and which reache to his neck. This pir must have died near the end of the last century, as persons now livin knew his son, Shah Imam Bukhsh, alias Chulu Meal Father and son lie buried close together. At the head of the grave of the former is placed the stor lattice on which he spent his twelve years meditation. The tombs are otherwise of no interest


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
	*****	iib	
	1 7		
		-	
			. 7
bandoned	Exploration desirable	iii	
		1	
5			
	1 0.8		






-				,
No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
				They are merely heaps of mud kept carefully clean and covered over with a grass thatch. In the same quarter a very large mesque formerly stood, which fell into ruins, when the proprietor sold the bricks to the Hindus of Náráyanganj. Muhammadans extenuate this offence by asserting that the proprietor, who was a pensioned Deputy Magistrate
	s 7 ,	*	+	was insane when he did it. Even the foundations have been dug up. It is said that the walls were 8 feet thick, and that the interior of the mosque was ornamented with carved bricks.
25	Dacca	Maghrápárá Sonárgaon.	Yasuffgañj Mosque.	On the roadside, east of Maghrápárá, is a small mosque called the Yasuffgañj Masjid. It is a very old one. The walls are nearly 6 feet thick, and this thickness combined with the strength of the masonry has kept the mosque still standing.
26	Do	Hábibpur, Sonár- gaon.	Tomb of Pagla Saheb.	Beyond the village of Hábibpur, on the right hand side of the district road, is the tomb of "Páglá Sáheb." It is an old insignificant building. Various stories are told of the reason why this pir received such a singular name. One is that he became light-headed, from the intensity of his devotions. Another, that he was a great thief-catcher, who nailed every thief he caught to a wall, and then beheaded him. Having strung several heads together, he threw them into an adjoining khál, which has ever since been known as the "munda málá," i.e., necklace of heads. This tomb is so venerated that parents, Hindu and Muhammadan, offer at it the "choti" or queue of their children when dangerously ill.
27	Do	Sadipur, Sonár- gaon.	Garibulla's Mosque.	This is situated on an elevated mound surrounded by a most in the village of Sadipur about half a mile north-east of Maghrápárá in the Sopárgaon pargana. It was erected by Sheikh Garibulla, formerly an examiner of cloth, to the East India Company. It bears the date A. H. 1182. Its pinnacles are made of glazed pottery, but the building generally is plain, and devoid of interest.
	-			
			-	

Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
4 1			
bandoned	. In ruins	iii	
	1900		
*****	Rapidly going to pieces. The	iii	
	trees, the roots of which have penetrated into the masonry.		
	Overgrown with vegetation and	iii	
*****	trees, and falling into decay.	144	
			1
			1000
Under the custody of An Hossein Mir, an inhabita	me to the trees, they want detrees	e	
of Barsechinish, a neighbo	his in bad condition and needs re	-	
forefather, Sheikh Garibu constructed this mosque.	four pillars at its four corner	0	-
	on. Deep-rooted pipul tree have grown into the walls an	35	
	the roof. The plaster of the lower parts of the wall he	10	1
	also fallen to the height of about 5' to 7' from the plinth level. The mosque do	16	
	not seem to have receive	ed o-	
	tion. The cost of these r pairs roughly estimated w come to about Rs. 250. Naw	in	
11	Ashannullah has recently pr vided this amount, and the	o- he	
	District Engineer will have	97	






No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
28	Dacca	Pannam, Sonar- gaon.	Dulálpur Bridge	This is a fine Muhammadan bridge over a khál on a village road connecting Pannam with the district road from Hájigañj to Byda Bazar. It has three arches, the middle arch is higher than those at the sides and is intended for the passage of boats. The bridge is very old. The roadway is very steep and is formed of bricks circularly arranged. There is also a smaller bridge leading from the same road over a branch khál to the main street of Pannam village. The roadway of this bridge is also formed of bricks arranged circularly and kept in place by several large pillars of hasalt laid flat at the toe or end of the arches. This bridge has towers at its sides which originally flanked a gate-way.
			3	
29	Do	Áminpur, Sonár-	Residence	In Aminpur lie the rains of the abode of the royal karori, or tax-gatherer. Like all old ruins, they are said to contain fabulous treasures protected by numerous snakes. A descendant of this family whose name is Káli Prasád Karori still resides in the neighbourhood; close to his residence are the ruins of an old Hindu building, the only one existing in Sonárgaon. It is called Jhikoti, and is a building having an elongated domed roof formed of concrete and walls pierced with numerous openings. It was formerly used for religious purposes.
30	Do	Goaldi, Sornágaon	Abdul Hámid's mosque.	This is a comparatively modern structure. Its kitaba bears the date A. H. 1116.
			1	
31	Do	Ditto, ditto	Mosque	About a hundred yards to the south of the above is the oldest mosque in Sonargaon. The residents call this old mosque purana or old mosque. Its kitaba has fallen out, but has been carefully preserved in the interior. On this stone is inscribed the name of Alauddin Husain Shah, A. H. 995. This monarch being an Arab assumed the title Sherif Mecca, but in this inscription he is designated "Hasabi," or Persian from the place of his nativity.
				The interior of the mosque is 16½ feet square. The four walls, as they ascend, give place to the eight walls of an octagon. At each corner are quarter domes or arches, and the dome rises from the pendentives. As usual there are three mihrabs or arched recesses. The centre one is formed of dark basaltic stones beautifully carved and ornamented with arabesque work. The two side ones are of brick, boldly cut and gracefully arranged. The bricks in the archways have been ground and smoothed by manual labour. The pillars at the doorways are sand-stone, evidently the plunder of some Hindu shrine. Until thirty-four years ago this mosque was used for


Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks,		
6	7	8	1	9	
Under the custody of Ram Chandra Poddar, Guru Chandra Poddar, and others of Pannam, who are well-to-do men and could easily keep the bridge in good order if so inclined. At present they are doing nothing for the protection or preservation of the bridge. The Collector hopes to get it taken over by the District Board as well as the smaller bridge.	The extremities of the paved roadway of the bridge about 22 feet on each side have sunk a little, but this settlement took place long ago, and there seems to be no danger that it will go further. Some trees have grown into the face of the bridge which should be rooted out. The bridge, has been much affected by the action of saltpetre, and requires repairs. New brickwork is needed in places, and soorkee plaster and pointing are also required. The cost of repairs will be about Rs. 410.	iiò			
		iii			
It is used by local worshippers who have abandoned the old one, and it is maintained by the Muhammadan inhabitants of the locality.	In good preservation	iò		-	
*****	This mosque is built of red brick. Its exterior was former- ly ornamented by finely carved bricks in imitation of flowers, but neglect, and the lapse of centuries have left few unin- jured.				
		1			





		1		
To.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
			+	worship. The makhadin or servant having died, no care was taken of the building. The dome threatened to fall in, so the worshippers migrated to the modern mosque.
32	Daoca	Pathorghata, tha- na Srinagar.	Mosque of Unwar.	The Masjid was built in Hijri 1102, i.e., 207 years ago, by one Unwar, a courtier of Emperor Alumgir Shah (Aurangzeb), and bears an inscription in front. It is 34' × 20' outside measurement, has one central dome and a smaller one on each side.
			3	
33	Do	Rájbári, tháná Munshiganj.	Mark (sames)	It is situated about 2 miles to the south-west of the Rajbari outpost. It is a monumental tower of brief masonry built, it is said, over the funeral pyro of the mother of Chand Rayya and Kedar Rayya who were about 300 years ago some independent prince of the locality. It is known as the Rajbari math It measures 30 feet square at base and about 80 feet in height and has a small room within it. The dimensions of the math are large and its proportion elegant. It stands up as a conspicuous landmar visible for many miles across the Ganges on the sout and the Megna on the north. The passenge steamers passing up and down the Ganges between Dacca and Goalundo have this math in sight for 4 or 5 hours, with an interval in the middle, at they pass it first going down the Ganges, and after wards again after rounding the point at the junt tion of the rivers, as they get up the Megna.
34	Do	Rámpál, thána Munshigaúj.	Bábá Adam's tomb and mos que.	The mosque is the only old building in Rámpál. I outside measurements are 49 feet long by 38 fe wide and the inside measures 33' × 22'. There is a tradition that the Burmese during the invasion took away the large pieces of stone from the corners of the walls, the jambs of the door and the springing points of the dones. The is a stone inscription on the front of the builting in a character no one in the neighbourhous and decipher. Tradition gives the date of erective
3	5 Do	Mirkadim, thán Munshiganj.	The Ballal bridge.	This is a strong structure of masonry and stands up the Mirkadim khál. It is said to have been bu by Rájá Ballál Sen before the conquest of Beng

Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- ention.	Remarks.
6	7	· 8	9
It is now under the charge of a Mollah or priest by name Jikan Khan, who lives near the mosque and enjoys an annual rent of Rs. 12-2 and the product of two pieces of rent-free pirottar land. It is used for daily prayer, and the above income goes to meet the expenses of lighting and mats, &c., that are used during the prayers.	It is in a good state of preserva- tion and is said to have been repaired to some extent about 20 years ago by one of the inhabitants of the locality who is now in indigent circum- stances. The late repairs have greatly improved the mosque, but some plants need rooting out, and some doors and repairs to floor are required. The cost of the repairs will come to about Rs. 250. Nawab Ashannullah Báhádur has supplied the amount, and the District Engi- neer is having the work done.	iiò	
It is not a place of worship and not in the custody of any particular person or used for any particular object.	It is neglected and much dilapidated. Large trees have grown in the masonry, and some of them have borne fruit. Saltpetre has also eaten away the plaster. It is only the strength of the masonry which has kept the Mot still standing. It has been estimated that the cotton trees can be eradicated and the pointing renewed for Rs. 700, towards which the Collector has raised Rs. 500. The District Engineer will see the work done.	ia	
The mosque is in charge of Ainuddin Khandkar, Muhammad Faizuddin Khandkar, and Mafizuddin Dewan, who live near the mosque and enjoy the produce of about 10 bighás of rent-free land for its maintenance. It is still used for worship and is much revered as a sacred place in the neighbourhood.	It is in a very dilapidated state. It has two stone pillars in the centre, which with the surrounding walls support a roof with six domes. Three of these domes have almost entirely fallen in, another is severely shattered, and the two last are intact. The whole of the building is overgrown with large trees, the roots of which have penetrated deep into the masonry, and the building cannot be repaired.	, -	See pages 132 to 135 of Vo XV of the Archeological Su vey Reports.
It is still used by pedestrians who cross the bridge over the narrow top of the wing walls.	The two south wings have fallen down, and the cut-waters are cracked. The whole structure		



No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
36	Dacca	Táltollah, tháná Srinagar.	Bridge	by the Muhammadans. If this is correct, it is about 800 years old. It consists of a centre Gothic such 14 feet span and 28 feet in height above the bed of the khál, with two side arches of 7 feet 3 inches span each, and 17 feet high. It is a fine bridge. The piers are 6 feet thick. The wings are straight back, and the whole length of the bridge is 173 feet. The abutments, piers, and arches, and the two north wings are entire. This bridge is also said to have been built by Rájá Baliál Sen. It is over the Táltollah khál. The capital of the Hindu Rájás was at Rámpál about two miles to the east of Munshigañj. Both this and the Mirkadim bridge stand in a direct line westward from the capital, over two parallel kháls, and it is said that they stood on a line of road running from the capital westward to the bank of the Pádmáriver. It consisted of three arches of masonry, of which 2 were of 15 feet opening each and the other of 30 feet. The larger arch was blown up by gunpowder during the first years of the English rule, so as to secure direct communication between Calcutta and Dacca, for large boats for the conveyance of troops, &c., to the Eastern frontier and for the Burmese wars.

(2) MYMENSINGH


37	Mymensingh	Goiyaripa Sherpur, Jámálpur division.	in	Fort ruins	An old fort built of mud. It has no architectural pretensions, but is of considerable size. It was built not less than 350 years, (and probably about 500 years) ago as an outpost, it is said, to check the incursions of the hill tribes. It is encompassed by three walls divided by two ditches, one between the outer and middle and the other between the middle and inner walls. There are four gates on the four sides of the fort. The east gate is called Koomdooári; the west gate is called Panidooári; the south gate Syám Shakarsdooári, and the north gate Khirkidooári. Two pieces of stone are lying near the Panidooári, and they are supposed to be a part of a door. A tombstone of Amir Hushen Sháh still stands within the fort. A big stone with an inscription in Arabic characters, which was placed on the tomb, was taken to the Asiatic Society, Calcutta in 1871. There is a boat-shaped island between the southern and western interior ditches called by some "Kosha" and by others "Dingá." There are several ponds within the fort, of which the Mati Miab Talao is well known. It is said that a powerful hillman lived in this place who would
----	------------	--	----	------------	--

Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.		
6	7	8	9		
The feat, however, is very dangerous.	is overgrown with large trees which have taken root in the masonry. The bridge needs thorough repairs, which will cost about 8,000 rupees. With such repairs the structure would be worth about 50,000 rupees, and the Collector thinks the work should be undertaken by the District Board.				
It is still used by people of the neighbourhood, who walk with extreme danger over the shattered arches and a light and narrow wooden footpath thrown across the demolished arch.	The gunpowder has totally destroyed the larger arch, and has so much shattered the other two arches and the piers that the restoration of the bridge is hopeless.	10			

DISTRICT.


No custodian	-		In a ruinous state, and the nothing about it worth pring.	ere is iii	
1		-			
-					
		-		100	
-					
		- 1			
		-			






No.	District.	Locality.	Name of monument.	History or tradition regarding the monument,
	2	3	4	5
				oppress travellers, and one Humaun Sha Amir killed him and built a fort here. Other say that Humaun Sha Amir, who was a nephew of the Emperor of Delhi, took refuge here from fear of the Emperor. During the quarrel between the Rájá of Kuch Bihár and Patkoor the Governor of Bengal, Mánsingha, put up here for a short time. The following is a copy of the translation made by the late Professor Blochmann of the stone inscription in the possession of the Asiatic Society:— "In the name of God, the merciful, the clament! There is no God but Allah. Mahomed is Allah's prophet "In the name of God, the merciful, the clament! There is no God but Allah. Mahomed is Allah's prophet O God, bless Mahomed, the elected, and Ali, the chosen, and Fatimah the pure, and Hassan and Hussain built the King of the age and the period Saifuldunaja Waddin Abdul Muzaffar Firoz Shah, the King—May God perpetuate his kingdom and his rule! This (vault) was completed in the blessed Ramjan 8 The slab of this inscription was in the Museum of the Asiatic Society, Calcutta having been sent down by Babu Hará Chandra Chaudhuri of Sherpur. It is of granite and measures 4 feet by 2 feet, but the letters are very indistinct, and many are hopelessly broken away. The inscription seems to have belonged to a vault. In each corner of the slab is a square, containing the name of one of the first khalifas; the two squares on the left and those on the right are joined by vertical lines, but the letters between each set of squares are illegible. The slab was entire, but an elephant put his foot on it, and the right side of the stone broke in two. The inscription itself consists of only four lines. This shows that the vault to which this inscription belonged was constructed in the reign of the Emperor Firoz Shah, who ruled from 1351 to 1388. This monarch is said to have been celebrated for his public works, and this fort was probably one of those works.
38	Mymensingh	Keshoregange	Temple of Lakshi Nárá- yaņ.	This temple consisting of 21 pinnacled structures, together with other adjoining buildings, viz. (1) the Jaltungi (summer house), (2) the Rāsbāri, (3) the Durgā mandir, (4) the Sib Mandir, and other smaller structures was erected about 150 year ago and are all dedicated to the god Lakshmi Nārāyan. They are known by the common name of Deb Mandir. Four tanks were also dug. One of these was a large piece of water, 265 yards in length by 142 yards in breadth. It is situated on the east of the temple of Lakshmi-Nārāyan. The Jaltungi or three-storied building rises from the bed of the tank in question. The temple of Lakshmi Nārāyan and its adjoining buildings cover an area of 9,216 square feet. There are two inscriptions in Sanskrit in the big temple, a considerable height from the base. Some of the letters are obliterated.

Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.
6	7	8	9
	1 1		
	2	1	
		1	
		-	
2	- 1		
	-		
			*
n the custody of Babus Lali	t Two of the buildings are i	n iib	
Das.	ruins.		
31			
		1 1	





No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	2	3	4	5
39	Faridpur	Khábáshpur, thá- ná Faridpur.	Mosque	Built by the great-grandfather of one Meheráli Khundakar of Khábáshpur, who was known as a fakir or darvesh amongst the people of his time.
40	Ditto	Mekchámi, tháná Baliakuṇḍi.	Temple of Bangsa Go- pál.	Built about 200 years ago by one Ajodhyárám Sen of the Baidya caste and dedicated to the family deity Bangsa Gopáljí.
41	Ditto	Batkamari, tháná Maksudpur.	Temple	Built about 100 years ago by one Subodha Roy, forefather of Jajüeśvar Sáhá of Batkamari. He intended to set up a Hindu idol named Siva in the temple, but did not succeed in doing so.
42	Ditto	Chuchs, tháná Maksudpur.	Dolmañcha temple.	Built about 70 or 80 years ago by one Padma Lochan Datta of Chucha for performing the Doljátrá. It is known as Dolmañcha.
43	Ditto	Pathrail, tháná Bhañga.	Mosque of Abda Khan- dakar.	Built about more than 200 years ago by one Abda Khandakar of Pathrail for the purposes of names or prayer.
44	Ditto	. Azampur, tháná Pangsa.	Mosque of Nasir Shaik.	Said to have been built some 200 years ago by on Nasir Shaik, a kotwal in the service of Rájá Rám jíban Roy of Nator, when the parganá Belgách was included in the zamindari of the Rájá.
45	Ditto	. Mathurápur, thán Belgáchi.	Temple	Sangram Shah of the Baidya family for dementors to some deity, but as one of the masons employed in its construction accidentally fell down from the steeple and died, it was abandoned.
46	Ditto	Dhobá dá ñg á tháná Bhusbaus	Temples of	Built about 300 years ago by one Durlabh Chandr
47	Ditto	Naliá Jámálpore, tháná Baliá- kándi.	Temple of	Built about 100 years ago by one Krishna Rás Chakravarti of Nalia and dedicated to the godder Jaya Durga.


(4) BACKERGUNGE


48	Backergunge	Bibi Chini, out- post Niámatí.	Bibi Chini's Mosque.	An old mosque raised on an artificial mound of considerable size and height. It is said to have been built by Bibi Chini, sister of Niyamatullah, who founded Niamati, and is evidently a relic of the time when the Muhammadans first settled in the district. It remained hidden in the jungle for centuries and was discovered at the time when the Sundarbans were cultivated.
----	-------------	-----------------------------------	----------------------	--

DISTRICT.

Custody or present use.	Present state of preservation and suggestions for conservation.	Classifi- cation.	Remarks.		
6	7	8	9		
n charge of Meheráli Khun- dakar of Khábáshpur and not used for any purpose.	In a dilapidated state. Is not much taken care of. Requires repairs.	iib			
The present owner is Basanta Kumar Sen. The temple has now been abandoned.	Overgrown with trees. Cost of repairs beyond the means of the present owner.	iib			
in charge of Jájnesvar Sáhá, but not used for any purpose.	Plants have grown over the top of the temple. Requires repairs and whitewashing.	iiò			
In charge of Nirmala Sundari, daughter of Raj Kumár Datta of Chucha. Not used for any purpose.	overgrown with Jungle, Me-	iib			
In charge of Abdul Rezzaque, son of Khandakar Neyazud- din, but not used at present.	Ditto ditto	iib			
The present owners are the zamindars of Belgachi, Manlavi Faiz Bux Chowdhury and others.	grown with trees. The present				
The present owner is Súrya- kumár Lahiri of Korokdi.	In a ruined state overgrown with trees. The steeple has come down. The present owner is well able to pay for substantial repairs.	3			
In charge of Mathurá Náth Sáhá and Dino Náth Sáha of Dhobádángá. The idol have now been removed from these temples and they are no used for any purpose.	places and are surrounded by jungle. Require repairs.	iib			
The present owners are Sash Bhūshan Chakravartí an others of Naliá.	In a ruined state and the owner are not able to make the necessary repairs.	s iib			

Is situated in the zamindari of Babu Lála Rájendra Kumár Singh Chaudhari, of Bakshi Bazar, Dacca, and is in his khás possession. Is not used in any way now.	***	***	iib	
		_	-	2







No.	District.	Locality.	Name of monument.	History or tradition regarding the monument.
1	- 2	3	_ 4	,5
49	Backergunge	Koshba, tháná Gour nadí.	Mosque of Sabi Khán.	Built by the man known as Sabi Khan. It is considerably superior in architectural merit to Bibi Chini's mosque. Its roof is supported by four stone pillars, which must have been brought from a great distance. There is a curious belief in the locality that of the four stone pillars which support the dome, one gradually decays and is reduced in size. After a few months the pillar again gradually reaches its original dimensions while another pillar decays. This process goes on in the four pillars. To test this legend the District Engineer, according to the Collector's instructions, has taken dimensions of the pillars as he found them on the 11th April 1895. These dimensions will be checked on his next visit.

DISTRICT-concluded.

Custody or present use.	Present state of and suggest conserva	preservation tions for tion.	Classifi- cation.	Remarks.		
6	7		8	9		
Is in the custody of Kazi Go- lám Mastafá, alias Madh Kázi.	Ruinous	***	iiò			
				*		








DACCA DIVISION.

Geographical Index to Ancient Monuments.

District,	Village.		Description of monument.				
1	2		3		1	4	
Backergunge	Bibi Chiqi	100	Bibi Chini's Mosque			80	
	Koshba	144	Mosque of Sabi Khan			33	
Onces	. Aminpur		Residence	400	444	-21	
	Dacco	41.0	Págla bridge	471	1000	11	
			Tungi do	100	10.11	10	
			The great katra (Cararanserai)	-44	444		
			The small do. (Carneanscrai)	444	10.0	1	
			The chak (market-place)		44.4		
			Armenian Church of the Holy Re	surrection	-54.6		
			The Lalbagh fort		***	4	
			Idgah of Mir Abdul Kassim Bibi Peri's manaoleum	***	10.00	-	
				Shahahaa	-4-	4.8	
			Mosque and tomb of Haji Kahjeh The Sat Gomal mesque		110	9 00	
			Harmond Thebra of F	***		- 4	
			Temple of Dhakesvari	***	*7.5		
			Do. of Jayakáli	144	45.5		
			Do. of Siva	-8.6	111	1	
			Tomb of Colombo Saheb	144	100	3	
			Tombs of Nawabs Nasarat-jan	g. Samsady			
			Kamaradawala, Gazinddin Hyd				
			Tomb of Shah Ali Saheb	422	90	E(
	March 1		Do. in Shahbag Park		200	14	
	Goaldi	213	Abdul Hamid's Mosque	14	1.14	21	
	-		Mosque	144	15.5	23	
	Habibpur	241	Tomb of Páglá Sáheb	***	49.0	21	
	Rajiganj	+=+	Fort	-14	97.9	11	
	Maghrápárá	100	Damdama Fort	***	***	19	
			Mohamed Yasni's morque	5 9 0	177	11	
			Lasufigani Mosque	444	44.1	21	
			Tomo of Munna Shah Darvesh	254	-14	14	
			, Shah Abdul Ala	200	171	1:	
	Minhadia		Valláli Bridge		***	2	
	Mirkudita Munshiganj	961	Exat.		788	1:	
	Naligani	941	Kadam Rasah Fort and Mosque		44.	11	
	Pannam		Dulalpur Bridge		77.7	21	
	Páthorghátá	pake.	Mosque of Unwar	***	161	2	
	Rájbári	***	Math (tower)	***	285	2	
	Rámpál		Baba Adam's tomb and mosque		EE-	2	
	Sadipur		Garibulla's Mosque	***	100	21	
	Sonakhanda	444	Fort ruins	-111	***	13	
	Sonargaon	44.5	Tombs of five pirs (saints)	2011	***	1s	
			Tomb of Ghyasuddin Azam Shah	4+4	321	1.	
	Taltollah	931	Bridge	44.6	555	2	
aradpur	A market beauty	pau	Mosque of Nasir Shaik		***	30	
	Batkamari		Templo	114	150	31	
	Chucha	141	Dolmancha temple	240	***	3	
	Dhobadanga	141	Temples of Kesab		10.0	30	
	100.00		Do. of Madan Mohan	144	-	3(
4	Khabashpur	444	Morqua		100	31	
	Mathurápur	3.8.6	Temple	***	***	31	
	Mekchami	***	Do. of Bangsa Gopal	112	8.8.4	3(
	Nalia Jamalpur	144	Do. of Java Durga	***	242	3(
Action to	Pathrail	140	Mosgne of Abda Khandakar	444	24.0	30	
lymensingh		486	Fort runs Temple of Lakshi Náráyan		***	26	
	Keshoregunge	10.00	Change of Labor, Agreemen	-011	491	28	




DACCA DIVISION.

Index of Ancient Monuments by classes.

		1	. 11	2		3		E
Ct	ANSIY	ICATION OF BUILDING.		District.		Village.		Pag
		Dalfloor		Danas		D		25
Bridges	199	Dulálpur Páglá	445	Do	57.4	Pannam Dacca	112	10
	4	Taleallah	-	The .	F F 7	Tale-fla	236	26
		Tungi	100	Do	110	Dacca	110	10
		Vallali		Do	1000	Mirkadim		2
hak (mark	et-	F87777		Do		Dacen	222	14
place).	***	Armenian Church of the	Holy	Do		Do		
		Resurrection.		-				
orts	200	Damdamá	+ + 4	Do	de.	Maghrápárá	144	1
		W 3 23 110000		Do	-	Hajiganj	155	1
		Kadam Rasul	170.70	Do	441	Naliganj	100	1
		Lalbagh		Do	5.50	Ditto	1.00	0
		******		Mymensingh Dacea	++1	Goiyaripa	100	2
		*****		73	144	Munshiganj	110	1
down le		Mir Abdul Kassim's		33.	***	Sonákhanda Dacca	1962	_
dgah	STREET,		ent)	73	***	Da	100	
intres (cara serais).		Mir Abdul Kassim's (gre Nawab Shaista I	Chan's	The state of the s	TRE	Do	0.00	
		(small).	E ALLEN O	190	419	2000	444	
fausoleum	4+1	Bibi Peri's		Do	44+	Do	***	
Tosques		Abda Khandakar's	611	Faridpur	***	Pathrail		3
		Abdul Hámid's	515	Dacca	+++	Goaldi	440	2
		Bábá Adam's		Do	5.45	Rámpál		1 5
		Bibi Chini's	***	Backergunge		Bibi Chini		8
		Garibulla's	944	Dacen	141	Sadipar		1 2
		241 111		Do	110	Goaldi	197	2
		Haji Khajeh Shahabag's	444	Do	223	Dagea	450	
		Kadam Rasul	294	Do	510	Natiganj	110	13
		******		Faridpur	271	Khahashpur	***	1 8
		Mohamed Yasuf's	1115	Ducca	***	Maghrápárá	***	1 3
		Nasir Shaik's	248	Faridpur	556	Azempur	.00	5
		Sabi Khan's	-116	Backergunge	144	Koshba	177	1 2
		Sai Gomal	***	Dacca	P43	Dacca	271.1	1
		Unwar's	845	Do	110	Páthaoghátú	***	1 2
		Yasufiganj	4.0	Do. ,	100	Maghrápárá	111	2
Palace	HAN	Husseni Dalan's	5-614	Do	71	Dacca	194	
Residence	494	23 (3 (1)		Do	8 2 7	Aminpur	F F7	1 3
emples	141	Bangsa Gopál		Faridpur	***	Mekchami	104	1 5
		The fibrate for		Ditto	2.0	Batkamari	***	3
		Dhákesvári	100	Dacos	914	Dacea	1600	
		Dolmancha	99.0	Faridpur	***	Chucha	n	1 3
		Jayakali	111	Dacca	0.66	Dacea	991	
		Jaya Durgá	21	Faridpur	***	Nalia Jamalpur	**	
		Lakshi Náráyan	117	Ditto Fashoromana	100	Dhobádángá	400	
		Madan Makan	201	Keshoregaunge Ditto	***	Mymensingh Dhobádángá		1 3
		Madan Monad	+44	Ditto	PPP	Mathurápur	100	
		Siva	711	Dacca	144	Dacca	***	3
Combs		Bábá Adam's		Do		Rámpál		
COM UN	***	Colombo Saheb's	4.14	The	283	Dacca	***	1 -
		Colombo Cimeb a	244	Do	***	Do	777	1
		Five Pirs'		Do	4.0	Same		1 :
		Ghyasuddin Azam Shah	442	Do	8,54	Dista	7.0	1
		Haji Khajeh Shahabag's		Do	-4-	Dacca	1011	4
		Munna Shah Darvesh's		Do	117	Maghrápárá	Her	
		Nawab Gaziuddin Hyde		Do	144	Dacea	119	
		Nawab Kamaradawala's	***	Do	350	Do	***	
		Nawab Nasaratjang's	***	Do	300	Do	100	
		Nawab Samsadwala's	161	Do		Do		
		Páglá Saheb's	***	Do		Hábibpur	0.61	1
		Shah Abdul Ala's	***	Do	24.7	Maghrapara	191	
		Shah Ali Saheb's	***	Do	244	Daces		
		Shaik Mohamed Yasuf's		Do	-	Maghrápácá		
lower (mat	h)	11711		Do	++4	Rajbari	100	
				A CONTRACTOR OF THE PARTY OF TH	-	111	2.00	







Central Archaeological Library,

NEW DELHI 22535

Bengal Public works Author Department

Tillet Deces Dir.

"A book that is shut is but a block"

GOVT. OF INDIA

GOVT. OF INDIA
Department of Archaeology
NEW DELHI.

Please help us to keep the book clean and moving.

5. 5. 118. N. DELNI.